

i AREAS OF APPLICATION

	Precision	All-round	Heavy duty
	Activities for which a high degree of sensitivity is required.	General work, also alternating tasks, for which a robust glove is required.	Rough work for which a very robust and abrasion-resistant protective glove is required.
	Examples: fine assembly, work with small parts (for example screws), operating control elements, final check	Examples: maintenance work, transport work, light metal work, normal assembly work, maintenance	Examples: heavy transport work (for example pallet transport), construction, maintenance work
Dry	ASH 1110 ASH 1240 ASH 4320 ASH 4520	ASH 2220 ASH 4340 ASH 4540	ASH 8250
Moist / slightly oily	ASH 1210 ASH 1215	ASH 2420	ASH 5225
Wet	ASH 6210	ASH 4560 ASH 6420	ASH 3420